

**MONUMENT RECORD**  
State of Indiana - County of Monroe

**Section:** 26

**Township:** 7 North


**Range:** 1 East

**Corner ID:** Polk S-21

**Monument Description & Remarks:** 3" Aluminum Cap, "U.S.D.A. FOREST SERVICE, UNLAWFUL TO DISTURB". Survey Sign 5ft above ground at pt. B

**References On File:**

RECOVERY TIE DRAWING  
Field Book 41 Page No. 72



- A - 3" Aluminum Cap
- B - N 33° E 7.55' to Survey Sign on 18" Beech Tree
- C - S 40° E 11.94' to MAG nail in 10" Black Oak
- D - S 70° W 35.09' to MAG nail in 10" White Oak

Not To Scale.  
Compass Bearing Magnetic North



26

I, Kevin P. Enright, Monroe County Surveyor, hereby certify that this document was prepared under my direction in accordance with the provisions of section 36-2-12-11 of the Indiana Code, and the above data is given under my hand and seal this 27th day of October, 2008.

*Kevin P. Enright*

Administered by the Monroe County Surveyor Review Board

Date: 4-7-2009



Index No. V-19  
(Alphabetical - Numerical)


LAND CORNER RECORD  
(RECTANGULAR SURVEYS)

R9-7 150-4 (Rev. 6/13/67)  
GPO 806-924

T. 2N R. 1E Mer. N.F. Hoosier County Monroe State Ind.  
36 Section Corner common to sections 36, 35, and

EXISTING SURVEYS

| Original Government Survey                                                           |  | Original Evidence Found                         |  |
|--------------------------------------------------------------------------------------|--|-------------------------------------------------|--|
| Year surveyed <u>1874</u>                                                            |  | Year of search _____ By _____                   |  |
| Original monument <u>Wood post</u><br>(Wood post, stone, pile of stones, pipe, etc.) |  | Monument found _____                            |  |
| Bearing Trees                                                                        |  | Original Bearing Trees Found                    |  |
| Species <u>Beech</u> <u>Poplar</u>                                                   |  | Species _____                                   |  |
| Diameter <u>18"</u> <u>6"</u>                                                        |  | Diameter _____                                  |  |
| Bearing <u>N 54° W</u> <u>S 26° W</u>                                                |  | Bearing _____                                   |  |
| Distance <u>9 1/2</u> <u>19 1/2</u>                                                  |  | Distance _____                                  |  |
| Subsequent Corner Restoration                                                        |  | Evidence of Subsequent Corner Restoration Found |  |
| Year surveyed <u>1878</u> By _____                                                   |  | Year of search _____ By _____                   |  |
| Where filed or recorded <u>County Survey Office - Monroe Co.</u>                     |  |                                                 |  |
| Monument <u>Stone</u><br>(Original, concrete post, iron rod, etc.)                   |  |                                                 |  |
| Bearing Trees, Reference Objects                                                     |  | Bearing Trees, Reference Objects                |  |
| Species <u>Beech</u> <u>Maple</u>                                                    |  |                                                 |  |
| Diameter <u>15"</u> <u>16"</u>                                                       |  |                                                 |  |
| Bearing <u>N 77° W</u> <u>N 60° E</u>                                                |  |                                                 |  |
| Distance <u>29 1/2</u> <u>8 1/2</u>                                                  |  |                                                 |  |



Sketch

○ Corner ☒ F.S. Land

At time of search:

1. Did you have the record description?

Yes ☒ No ☐

2. How was search area located?

Pacing, chaining, photos, maps,  
etc. photos, maps

3. Man hours spent in search 1 1/2

man hours

4. Do you think additional search might

recover evidence? Yes ☐ No ☒

5. Signature H. Weston

Relation of Evidence to Record Features Along Section Lines

Section line to sections 26-25  
Object Creek  
Record distance 10 ch. E to Power  
Measured distance \_\_\_\_\_

Other Evidence

Describe evidence of use and occupation such as roads, fences, clearings, timber cutting lines, plantations, etc.. Cite source of testimony if any. Found fence corner  
But no evidence at corner being monumented.  
Fence runs N 1 E

Perpetuation Record

Monument and accessories established. Include brief description of area. \_\_\_\_\_

Creek lies 10 ch west of 1/4 Sec. corner  
monumented in deed 11-01-49 (Ed H. Henberg to U.S.)

Did not measure 10 ch from creek

Certified corner restoration certificate prepared: Yes ☐ No ☐

Filed in county records at \_\_\_\_\_ Date \_\_\_\_\_ County Document No. \_\_\_\_\_

Identified on aerial photo No. \_\_\_\_\_ Which is filed at \_\_\_\_\_